

Appendix B

Dearborn County Government
ADA Compliance (Self-Evaluation)

SYSTEM	CORRECTION	DISTRESS	QTY	EST COST	COMMENTS	URGENCY LEVEL
	ADMIN BUILDING					1, 2, 3
Ramps	Over 6 ft - add railings on both sides	Inadequate	1	Campus		3
Ramps	Need 36" clear width, ours is 32"	Inadequate	1	\$ 1,100		3
Ramps	Cross slope exceeds 1:48	Inadequate	1	Campus		3
Doors	Levers need installed @ B-1, B-2, B-6, B-7, Maint Ofc, Nurse 1&2, 100, 101, 102, 106, 103G, 103P, Recorder's, Corrections Main, Bldg Comm., 200, 201, 202, 203, Assessor, Auditor, HR, Treasurer, 300, 301, 302, 303A, 303B, 304, 305, 306, P&Z, and Surveyor	Missing	35	\$ 7,350		2
Doors	Bldg dept main doesn't swing to path of egress	Inadequate	1	\$ 500		3
Doors	18" clearance needed on latch sides of doors @ Health Dept#306, both Comm. doors 303A/303B, Surveyor 302(pole in way)	Inadequate	4	Not Feasible	Committee to discuss alternative methods to make accommodations.	N/A
Rooms and Spaces	36" wide path to services (health dept.)? 36" wide path in HR	Inadequate	2	Moving		Moving
Signage	Need "handicap bathroom available" on 1 st floor.	Missing	1	\$ 53		1
Signage	B2 needs signage	Missing	1	\$ 53		1
Signage	Main Entrance signage	Missing	1	\$ 53		1
Signage	106 Door signage (probation)	Missing	1	\$ 53		1
Signage	Commissioner Conference Room sign	Missing	1	\$ 53		1
Signage	Surveyor's Office sign	Missing	1	\$ 53		1
Signage	1 st & 2 nd Floor sign height (60" to center)	Inadequate	2	\$ 53		1
Controls	Relocate emergency fire pull by Bldg dept	Inadequate	1	\$ 500		2
Counters	Following counters are all 42": Bldg dept, Recorder, Receptionist, Auditor, Treasurer, Assessor, Health, P&Z-they should be 28-34" or service counters 36"	Inadequate	8	Campus		2

Appendix B

Dearborn County Government
ADA Compliance (Self-Evaluation)

Bathroom	M/W stalls need lever for closed fist op	Missing	1	\$ 50		1
Bathroom	M/W lavs skirting are 28", should be 29"	Inadequate	1	Campus		2
Bathroom	M/W mirrors are 41.5", should be 40"	Inadequate	1	\$ 100		1
Pay Phone	Needs to be Hearing Aid compatible, Height is 55", should be 54", Protrudes more than 4" into path, needs cane detection	Inadequate	1	\$ 300		1
COURT HOUSE						
Doors	Levers need installed @ Basement Conf rm, break rm, SC prob, SC prob ofc, pros doors 1&2, SC2, SC2 prob, SC2 prob ofc, CC chambers, JC rm, CC ofc 1, CC ofc 2, CC courtn, CC clerk, prob ofc(jury), CC(jury)	Missing	21	Historical		N/A
Doors	Path of egress swing over 50 occ. Must wing in path of egress - CC door, CC clerk door, SC Door, CC prob doors	Inadequate	4	Historical		N/A
Signage	Conference room	Missing	1	\$ 53		1
Signage	Break room	Missing	1	\$ 53		1
Signage	Elevator	Missing	1	\$ 53		1
Signage	Superior Court II	Missing	1	\$ 53		1
Signage	Exterior HDCC accessible	Missing	1	\$ 53		1
Counters	CC prob counter is 42". Service counter heights should be 36"H.	Inadequate	1	Campus		2
Counters	Pros receipt counter is 50" should be 36"	Inadequate	1	Campus		2
Counters	CC counter is 41" should be 36"	Inadequate	1	Campus		2
Counters	CC clerk count is 41 3/4" should be 36"	Inadequate	1	Campus		2
Counters	Sup Court counter is 42" should be 36"	Inadequate	1	Campus		2
Tables	CC tabe is 24 3/4" knee clearance should be 28"-34"	Inadequate	1	Campus		2
Tables	Juvenile tale is 24 3/4" should be 28"-34"	Inadequate	1	Campus		2
Tables	Sup Court table is 25 3/4" should be 28"-36"	Inadequate	1	Campus		2
Pay Phone	Needs to be Hearing Aid compatible, Height is 55", should be 54", Protrudes more than 4" into path, needs cane detection	Inadequate	1	\$ 300		1

Appendix B

Dearborn County Government
ADA Compliance (Self-Evaluation)

LAW ENFORCEMENT CTR								
Ramps	Needs handrails	Inadequate	1	Campus				3
Ramps	Needs to be 36" width, it is 33 1/2"	Inadequate	1	\$ 800				3
Parking Drop off area	Van accessible handicap spot should be 16' space - we have 15'5"	Inadequate	1					1
Entrance	Curb ramp 1 3/8" in 12"	Inadequate	1					3
Doors	Need 18" clearance on pull side of doors, we have 13"	Inadequate	?	Not Feasible	Discuss alternative mechanisms for accomodation			Infeasible
Doors	Main sheriff door needs lever and operator	Inadequate	1	\$ 210				2
Doors	Sheriffs door needs lever	Inadequate	1	\$ 210				2
Signage	Need signs at all floors	Missing	?	\$ 53				1
Signage	Need sign at service counter	Missing	1	\$ 53				1
Signage	Need signs at restrooms	Missing	?	\$ 53				1
Counters	Service counter height is 47 3/4" should be 36"	Inadequate	1	Campus				2
Restrooms	Mirrors are 48" should be 40"	Inadequate	?	\$ 100				1
Drinking Fountains	Needs cane detection	Inadequate	?	\$ 300				1
Pay Phone	Needs to be hearing aid compatible.	Inadequate	?	\$ 300				1
Ramps	<u>Emergency Mgmt</u> Slope should be 1" in 12", it is 1.5" in 12"	Inadequate	?	\$ 5,300				3
Ramps	Needs handrails on both side	Missing	?	\$ 6,000				3
Entrance	Needs 18" of clearance on pull side of door	Inadequate	?	Not Feasible	Discuss alternative mechanisms for accomodation			N/A
Doors	Levers need installed @ main entrance, Director ofc door, hall door, bathroom doors	Missing	5	\$ 1,050				2
Signage	Need signs for entire building	Missing	5	\$ 263				1
Bathroom	Needs signs	Missing	3	\$ 158				1
Ramps	<u>Juvenile Center</u> 1 1/4" in 12" on initial and second ramp, top ramp 1" in 12"	Inadequate	3	\$ 3,200				3

Appendix B

Dearborn County Government
ADA Compliance (Self-Evaluation)

Signage	Need sign at main entrance	Missing	1	\$	53	1
Restrooms	Need additional grab bar back of toilet	Missing	?	\$	64	1
	Highway Department					
Signage	Needs signs for handicap parking and unloading areas, main entrance, main counter	Missing	4			
Restrooms	Need grab bars in both restrooms	Missing	1			
	Soil and Water					
Signage	Need signs for farm services and NRCS	Missing	2			
Tables	Knee space is 25.5 needs to be 27	Inadequate	1			
Doors	Sign on door needs to be on latch side of door 60" centered	Inadequate	1			
	YES Home					
Ramps	Ramps over 6" needs handrails. Ramp is 27" long	Inadequate	1			
Entrance	Entrance doors need to be 32". Every door is 30"	Inadequate	?			
Entrance	Door closer should be at least 3 seconds to close, this one is 2 seconds or less	Inadequate	1			
Signage	Need sign on main entrance and inaccessible entrances	Missing	1			
Signage	Need elevator sign and stair with Braille 60" center	Missing	?			
Tables	Need one table with 34" height and 27" knee clearance	Missing	1			
Elevator	Call buttons need to be 42" they are 47.5". Need to provide a reach stick	Inadequate	1			
Restrooms	Need additional grab bar back of toilet, Lavatory rim 1" low in both	Inadequate	?			
Restrooms	Knee area us 2" low in both	Inadequate	2			
Restrooms	Mirrors are 43.5" high in both	Inadequate	?			
Drinking Fountains	Need cane detection it is located w/in 27" of floor and protrudes over 4"	Inadequate	?			
	Dillsboro Park					

Appendix B

Dearborn County Government
ADA Compliance (Self-Evaluation)

Signage	Need sign on non accessible restrooms giving direction to ADA compliant restrooms	Missing					
Yorkville Park							
Parking	Mark unloading zone	Missing					
Play areas	No accessible play areas	Missing					
Accessible Routes	No accessible routes to play areas, restrooms or pavillion	Missing					
Women's restroom	stall to small, sink incorrect, no mirror, towel dispenser too high, need braille sign, handle too high, concrete pad at entrance sunk creating obstruction	Inadequate					
Men's restroom	sign missing, handle too high, towel dispenser too high, soap dispenser too high, sink incorrect, concrete pad at entrance sunk creating obstruction	Inadequate					
Bright Meadows							
Parking	Restripe, needs sign	Missing					
Play areas	No accessible play areas	Missing					
Women's restroom	Needs tapered threshold, mirror and lever on entry door	Missing					
Men's restroom	Needs tapered threshold, mirror and lever on entry door	Missing					
Animal Control @PAWS							
Signage	Need sign for employee door only	Missing					
Campus Rail							
				\$	4,450		
Campus Counters/Tables							
				\$	2,210	TOTAL COST	\$
Hoosier Square Rail							
				\$	9,910		
Signage All Facilities							
				\$	20,436		
							\$
							66,000